

Imray Correction Notice

16 April 2012

ICC14-1

Chart C14 WGS 84

Edition Aug 2010

Date of printing Aug 2010

The following corrections should be noted:

1 River Lynher (Inset)

Amend vertical clearance of viaduct to 18m in 50°23'·85N 4°16'·98W (ILNW 551/10)

2 Hamoaze, Western Mill Lake

Insert minor Lt at end of pontoon in 50°23'·56N 4°11'·23W (ILNW 87/11)

3 Cattewater, Clovelly Bay (Plan A) (buoy moved - see ILNW 193/11)

Insert G con Lt buoy Fl.G in 50°21'·57N 4°07'·43W (ILNW 142/11)

4 Cattewater (Plan A)

Move G con Lt buoy Fl.G in 50°21'·57N 4°07'·43W to 50°21'·67N 4°07'·43W (ILNW 193/11)

5 Hamoaze, Kinterbury Point southeastwards

Delete Y spher Lt buoy Fl(5)Y.20s (3 buoys) in 50°23'·53N 4°11'·91W (ILNW 233/11)

6 Hamoaze, Henn Point

Amend Lt bn to Fl.WRG.2s5m5/3M in 50°23'·95N 4°12'·72W and add Lt sectors: **306°-G-318°-W-320°-R-328°** (ILNW 367/11)

7 Hamoaze, Carew Point

Amend Lt bn to Fl.WRG.2s5m5/4M in 50°23'·56N 4°12'·70W and add Lt sectors: **196°-G-198°-W-202°-R-204°** (ILNW 368/11)

8 River Yealm entrance (Inset)

Insert RW bn with rectangular topmk in 50°18'·81N 4°03'·67W.

Add ldg line from RW bn in 50°18'·83N 4°03'·65W, extending in direction 227°, plus lgd 047° at seaward end. (ILNW 418/11)

9 Saltash northeastwards

Insert Wk depth 1·6m in:

50°24'·96N 4°12'·35W

50°25'·11N 4°12'·29W (ILNW 136/12)